CHEM-FEED® Chemical Feed Systems

PVC

Flex-Pro Pumps 1/4" ID Tube Compression Connections

Dual Skid Shipping Kit

Part No.	Description	Quantity	Picture
76001-538	Adapter - ½" Slip to 3/8" OD Tube Glue into skid for 1/4" tube connection to pump.	4	
90008-305	Tube Nut Compresses 1/4" tube to adapters.	8	
76000-296	Tubing - 1/4" ID (3/8 OD) Suction tubing for pump.	5 ft x 2	
76000-168	Tubing - 1/4" ID Discharge tubing for pump.	5 ft x 2	
76001-487	Adapter - ½" Slip to ½" Hose Barb Glue to main inlet and outlet valves of skid.	3	
73000-159	Threaded Ball Valve Ends Optional threaded ends for ball valves.	3	
76000-296	Tubing - 1/4" ID (3/8" OD) Connect to calibration cylinder for air release. For 8, 16, and 32 GPH calibration columns	5 ft x 1	
76000-171	Tubing - 1/4" OD Connect to calibration cylinder for air release. For 1.6 and 4 GPH calibration columns.	5 ft x 1	
90008-364	Extended Bracket Attached to bottom of pump.	4	

Part No.	Description	Quantity	Picture
90011-122	Screw 10-32 x .50 Phl. Pan Head Attaches bracket to pump.	8	
90011-195	Screw 10-32 x.62 Soc. Head Mounts pump onto skid using brackets provided.	8	
90011-026	Nut 10-32 Hex Used along with screw #90011-195 to mount pump to skid.	8	
90011-094	Washer #10 Use 2 washers per screw #90011-195 and nut #90011-026 to mount pump to skid.	16	
90008-162	Allen Wrench "5/32" Used on 10-32 screws for mounting pump to skid frame.	1	
90008-249	Allen Wrench "3/16" Used on 1/4-20 screws for securing/mounting the skid frame.	1	
90008-443	Drip Tray	2	
80000-462	Instruction Manual	1	CHEM-FEED B Authorises
80000-469	Quality Certificate	1	Controlled in former and speed. Soft Trees. The state of the state o
80000-470	Quick Start Guide	1	

Note: Instruction sheets that come with calibration column, pressure relief valve, and ball valves should also be included in this shipping kit.